

## Repair instruction

**Description: C2 C3 C4 (produced until 15 June 2000) Lip seal**

**Part number: 16175**

Look for Service Centers, Point of Sale addresses and other information on: [www.thetford-europe.com](http://www.thetford-europe.com)

**Version:** V2

**Date:** 13/07/2006

**Tools required:** 


**A**

Unscrew the 8 screws on the seal cover and, take the seal cover off.



**B**

Ensure the two cut outs on the seal face upwards and line up with the two centre screws of the three positioned on either side of the seal cover.



**C**

Replace the seat cover.



13/07/2006

Description: C2 C3 C4  
(produced until 15 June  
2000) Lip seal

1