

## Repair instruction

**Description: C2 C3 C4 Float vent (produced before June 1993)**

**Part number: 21510**

Look for Service Centres, Point of Sale addresses and other information on: [www.thetford-europe.com](http://www.thetford-europe.com)

**Version:** V1

**Date:** 17/01/2007

**Tools required:** -

**A**

Waste tank C2 C3 C4.

Enter the waste tank with the float vent ensuring the vent is flat side up.





**B**

Position the float vent as shown in the picture.



**C**

Push the float vent beneath the blade arm driver.



17/01/2007

Description: C2 C3 C4  
Float vent (produced  
before June 1993)

1